

OIL SPILL RESPONSE EQUIPMENT STATUS: UKDS Dispersant Stockpile

The attached equipment report is to be used for guidance purposes only. Response strategies should not be based solely on this report.

STO	CKPILE DESCRIPTION	Total m ³	Total US Gal	Spill Use	Other	Available %
Inverness, Scotland						
	Slickgone NS	200	53,000	0	0	100%
Scalloway, Shetlands						
	Slickgone NS	300	79,500	0	0	100%
	Total	500	132,500	0	0	100%